

CHIMNEY SWEEP AND LEVEL ONE INSPECTION

Appliance Service Record

HIGH MOUNTAIN HEARTH SOLUTIONS, INC.
 18573 G RD
 DELTA, CO 81416
 970-874-4328 (HEAT)



Woodcreek Lodge

| Unit Number | Date/Time | Type of Appliance and Chimney |
|-------------|------------|------------------------------------|
| 504 | 04/23/2019 | Manufactured Fireplace and Chimney |

Photo



MANUFACTURED FIREPLACE

Each component is inspected and serviced as needed to ensure safe and proper operation

| | Acceptable | Unacceptable | Not Applicable | Comments |
|---------------------------|----------------------------------|-----------------------|-----------------------|--|
| Firebox | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | Replaced defective fireplace floor |
| Refractory | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | |
| Doors | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | |
| Damper | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | |
| Hearth Extension | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | |
| Clearance to Combustibles | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | Installed heat shield to provide adequate clearance to sidewall. |

MANUFACTURED CHIMNEY

Each component is inspected and serviced as needed to ensure safe and proper operation

| | Acceptable | Unacceptable | Not Applicable | Comments |
|-------------|----------------------------------|-----------------------|-----------------------|----------|
| Height | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | |
| Condition | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | |
| Chimney Cap | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | |

INSPECTION CONCLUSION

Results

Performed Chimney Sweep and Level I Inspection, and ensured chimney is free of dangerous creosote deposits. All conditions satisfactory.

Comments:

| |
|--|
| |
|--|

Powered by www.doForms.com