

**CHIMNEY SWEEP AND LEVEL ONE INSPECTION**

Appliance Service Record

HIGH MOUNTAIN HEARTH SOLUTIONS, INC.  
18573 G RD  
DELTA, CO 81416  
970-874-4328 (HEAT)



**Woodcreek Lodge**

Unit Number	Date/Time	Type of Appliance and Chimney
102	05/28/2019	Manufactured Fireplace and Chimney

**MANUFACTURED FIREPLACE**

Each component is inspected and serviced as needed to ensure safe and proper operation

	Acceptable	Unacceptable	Not Applicable	Comments
Firebox	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
Refractory	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
Doors	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
Damper	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
Hearth Extension	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
Clearance to Combustibles	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Installed wall shield to provide adequate clearance to combustible materials in the event the electric fireplace is removed and the fireplace is used to burn wood.

**MANUFACTURED CHIMNEY**

Each component is inspected and serviced as needed to ensure safe and proper operation

	Acceptable	Unacceptable	Not Applicable	Comments
Height	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
Condition	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
Chimney Cap	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	

**INSPECTION CONCLUSION**

<b>Results</b>
Performed Chimney Sweep and Level I Inspection, and ensured chimney is free of dangerous creosote deposits. All conditions satisfactory.
<b>Comments:</b>
Electric fireplace was removed and reinstalled after service.